

Bolt Action Centerfire – Bolt Lock Update Modification Program
Website text

Remington Model 30 and 30 Express bolt-action rifles are not included in the **safety modification program**. These rifles were manufactured from 1921 until 1940. However, these old firearms do have a bolt-lock mechanism, which requires the safety to be placed in the “f” or “fire” position to unload and load the rifle. As with any firearm, special care must be taken during the loading and unloading process. Always keep the muzzle pointed in a safe direction. Keep the safety in the “S” or “safe” position at all times until you are ready to shoot. Always unload your rifle when not actually in use. Every firearm should be unloaded as soon as you are finished shooting – before taking it into your car, camp or house. Remington wants you to enjoy the shooting sports safely!

Should you desire service on any of your Remington firearms please feel free to call us on our toll free service line @ 800 243.9700. Visit the Remington authorized repair center nearest you [insert link].

6/12/2006

1