

Bolt Action Centerfire – Bolt Lock Update Modification Program
Website text

Remington Model 725 rifles were manufactured by Remington from 1957 until 1962. Remington Model 725 rifles have a three-position safety, which permits those rifles to be unloaded with the safety in the “mid” position. Model 725 rifles are not included in the **safety modification program**. Nevertheless, special care must always be taken during the loading and unloading process of this and any firearm. Keep the safety in the “S” or “safe” position at all times until you are ready to shoot. Always keep the muzzle pointed in a safe direction. Always unload your rifle when not actually in use. Every firearm should be unloaded as soon as you are finished shooting -- before taking it into your car, camp or house. Remington wants you to enjoy the shooting sports safely!

Should you desire service on any of your Remington firearm please feel free to call us on our toll free service line @ 800 243.9700 . Visit the Remington authorized repair center nearest you [insert link].

6/12/2006

1