

Bolt Action Centerfire – Bolt Lock Update Modification Program
Website text

Remington Model 788 bolt-action rifles are not included in the **safety modification program**. Model 788 rifles were manufactured by Remington from 1967 until 1983. Those Model 788 rifles made before 1975 were equipped with a bolt-lock mechanism. If you have a Model 788 rifle with a bolt-lock mechanism, the safety must be placed in the "F" or "fire" position to load and unload the rifle. Regardless of whether your Model 788 rifle has a bolt-lock mechanism you must always follow the 10 Commandments of Firearm Safety. Special care must be taken during the loading and unloading process. Always keep the muzzle pointed in a safe direction. Always unload your rifle when not actually in use. Every firearm should be unloaded as soon as you are finished shooting – before taking it into your car, camp or house. Remington wants you to enjoy the shooting sports safely!

Should you desire service on any of your Remington firearms please feel free to call us on our toll free service line @ 800 243 9700. Visit the Remington authorized repair center nearest you [insert link].

6/12/2006

1