

Bolt Action Centerfire – Bolt Lock Update Modification Program  
Website text

Remington Model Seven and 710's are not included in the **safety modification program**. These rifles have been manufactured since 1982 and, therefore, do not have a bolt-lock mechanism. As a result these rifles may be loaded or unloaded with the safety in the "s" or "safe" position. Nevertheless, as with any firearm, special care must be taken during the loading and unloading process. Keep the safety in the "S" or "safe" position at all times until you are ready to shoot. Always keep the muzzle pointed in a safe direction. Always unload your rifle when not actually in use. Every firearm should be unloaded as soon as you are finished shooting – before taking it into your car, camp or house. Remington wants you to enjoy the shooting sports safely!

Should you desire service on any of your Remington firearms please feel free to call us on our toll free service line @ 800 243.9700. Visit the Remington authorized repair center nearest you [insert link].

6/12/2006

1