

Bolt Lock Update Program
Model 700, 600, 660 xp-100, 40-x

Walks into Gunsmith

Determine model and
year of manufacture

Review options
with consumer and
obtain direction from them

Options

700, XP-100, 40-X

- Clean and inspect and ...removal
- Clean and inspect and bolt lock removal
- Fire control replacement

600, 660

- if already repaired under the 1979 recall
 - Clean and inspect and ...removal
 - Clean and inspect and bolt lock removal
 - Fire control replacement
- If not repaired under the recall -
 - New fire control without bolt lock feature (F

Review firearm
Complete trigger assembly
checklist.

Discuss options with
consumer based on review of
firearms

Proceed with repair per
instructions from consumer

Charge according to
reimbursement schedule

Return gun to consumer

if firearm is in unsafe
condition and customer
denies service have denial of
service completed


Complete Paperwork
- warranty form
- Trigger assembly Checklist
- Denial of Service

- Trigger assembly Checklist
- Denial of Service
and send to Remington

CONFIDENTIAL

FREE to Consumer)

**Bolt Lock Update Program
Model 721 or 722**



- warranty form
 - Trigger assembly Checklist
 - Denial of Service
- and send to Remington