

# LIMITED DISTRIBUTION

PRODUCT SAFETY SUBCOMMITTEE MEETING  
OCTOBER 23, 1978

PRESENT:

SUBCOMMITTEE

E. F. BARRETT, CHAIRMAN  
R. A. PARTNOY  
E. G. LARSON  
E. HOOTON

OTHER

J. H. CHISNALL  
J. E. PREISER  
A. W. BELL  
H. D. ALBAUGH  
E. S. McCAWLEY  
R. B. SPERLING, ACTING SECRETARY

MOHAWK MODEL 600, ETC.

The John Coates case, involving the accidental discharge of a Mohawk Model 600, was settled today for \$6,800,000. Remington's investigation into the case indicated that it was unlikely that the gun fired without the trigger being pulled, but that it was possible due to the fact that the safety selector and the trigger can be manipulated in a way that subsequently moving the selector to fire can lead to an accidental discharge. In light of the ramifications of this case, the Subcommittee decided to recommend to the President that the Mohawk Model 600, as well as the guns with similar trigger assemblies, Remington Model 600 and 660 and the XP-100, which were manufactured before February, 1975, should be recalled.

Since the guns can be fixed by the substitution of a new trigger assembly, the Subcommittee determined that the most expeditious method to affect this correction would be to refer gun owners to the nearest Remington recommended gunsmith in their area.



NTBOOK059

Sperling S