

**RESEARCH DEPARTMENT
JANUARY 1982**

**REASONS FOR
REMOVAL OF "CONNECTOR"**

- 1. ELIMINATE A PART**
- 2. INSURE A MORE POSITIVE LIFT**
- 3. MAINTAIN PROPER CLEARANCE**



NTBOOK166