

GUNSMITH MANUAL

WHEN REPAIRING TRIGGER HOUSING ASSEMBLY WASH PARTS THOROUGHLY WITH A PETROLEUM SOLVENT. AN ACCUMULATION OF GUN OIL OR DRIED OIL CAN BUILD A FILM THAT MAY CAUSE MALFUNCTIONS. RELUBRICATE WITH A DRY LUBRICANT AND REASSEMBLE.