

GUNSMITH CALL REPORT

Date 7/25/83 Reporter Donald McClure

Shop Name C. Wheeler Guns & Gunsmith Ser. Gunsmith's Name C.F. Wheeler

Address 1908 E. George Washington Way Richland, WA, 99352

No. & Street City State Zip

Gunsmith on Premises? Yes If not, give address below:

Gunsmith's Address    Zip

No. & Street City State

Recommended List (X) Open Acct. (X) % Disc. 30% Dealer (X) Large ( ) Small (XX)

PERSONS INTERVIEWED and POSITION: NEW GUN REPAIR

1) C. Wheeler - Owner/Gunsmith (2)

3)  (4)

SPECIFIC PROBLEMS ENCOUNTERED:

1. M-700 - Guns fire when safety switch moved to off position.
2. M-1148 - 12 Ga. - Needed oversize locking block.

GENERAL DISCUSSION

Mr. Wheeler told me they have had 5 M-700's in the last year which the owners claimed fired when the safety was pushed to the off position. All were returned to Arms Service per our instructions. The guns came back with new triggers installed but no explanation of what, if anything, was found wrong. He said a couple of the gun owners were unhappy because their gun had to be sent to the factory, but he told them that was Company policy, so they accepted it.

Still some M-1148 shotguns coming in; usually need an oversize locking block to correct the problem.



J-17