


Form letter #1 ~1700



Sept. 5, 1989

Dear Sir,

I recently won a NRA contest and one of the prizes was a Remington Model 700 ADL, ser. # C6310171 in 30-06 caliber. I am disappointed in the iron sights but am pleased with the overall rifle. My complaint is that to zero in the sights I must move the rear sight to the extreme left. In your literature you state that the weapon has been zeroed in at 100 yards at the factory. This is not the case with my weapon and having the rear sight to the extreme left is not a good situation from a "potential damage and catching on things" point of view.

I own several rifles including a 7600 and none of them have the rear sight to one of the extremes but are reasonably centered.

In addition, the "white dot" on the front sight is not uniform i.e. instead of  it is .

These complaints may not be a big deal but are a cause of customer concern and suspect quality. If the "little" things are not first class what about the hidden "big" things.

I still like the feel and shooting accuracy of the rifle.

Sincerely yours,

Kenneth Abte

P.S. over