0 - 1 ... #8778

This firearm has the following defect: Fare on Chrosing

and Sofety. See constoners note:

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Morristown, MN 55052