

Cust Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 027088
 OUTSIDE WORK: NO DATE: 12-18-72
 FIRED AMMO TYPE: - FROM: VALLEY HOME SUPPLY CO.
 & CONDITION: ASSEMBLER - P MILES BURG, PA.
 PROOF: R.E.P.-D INSP.: 9 TEST: 13 GUN #: 6261266
 HEADING: O.I.C. CODE: OS = 7/69
 BREECH OPENING: - GA./CAL.: 308 WIN.
 RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

EVIDENCE OF TRIGGER BURRS BINDING. TRIGGER 1.074
 (MODEL DRAWING 1.076) EXCESSIVE LUBRICANT - TOO HEAVY.
 TRIGGER CONNECTOR - SEAR ENGAGEMENT .015 (MIN. 13.020)

COMPLAINT: "FIRED WHEN SAFETY WAS RELEASED"

INCIDENT: FOLLOW-DOWN.

COMMENTS: THE TRIGGER BIND, HEAVY LUBRICANT COMBINATION
PROBABLY CAUSED THE FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3190

AL 0029720