

RECEIVING AND ESTIMATING REPORT

CUST NO: 002719 WILM		COMMENTS	
INITIAL	CUSTOMER ORDER NO.		
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
10/07/91	10/09/91	BA 1-B0	A6B67840
ACCESSORIES	W/STUDS		MODEL AND GRADE
			700 22-250 VAR BDL
FROM:		SHIP TO:	
AHLMANS ROUTE 1 BOX 20 MORRISTOWN USA		AHLMANS ROUTE 1 BOX 20 MORRISTOWN USA	
ACCOUNT NUMBER		ACCOUNT NUMBER N/C	
WRITE ☐		CLEAN/TEST	
PROM. DATE		ESTIMATED	
		10-18-91	
VIA		UPS	

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Fires when opening bolt.

MAIN FAULT

Find no fault! Cannot duplicate complaint, rifle operates properly in every respect.

Trigger pull 5 1/2 #; rear-let .010"

ARTS

#	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	DE					
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

Refer to return rifle as-is, or, we can install new trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.

OFFICE COPY

RD6925 REV. 7/90

PPS 00073