

# 8521

TO: Rem.

This firearm has the following defect: hangfires,  
abnormal safety operation,

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding. Thank you.

**AHLMAN'S INC.** Rt. 1, Box 20, Morristown, MN 55052