

RECEIVING AND ESTIMATING REPORT

CUST NO 985749 NYLH		COMMENT: L2 BLACK TIP ON STOCK	
B	CUSTOMER (ORDER) NO. 90859	DATE RECEIVED 1/28/91	DATE ORDERED 08/29/91
DATE CODE KZ 5-75	SERIAL NUMBER 6854937	MODEL AND GRADE 700 25-06	ORDER NO. R 91-17097
ACCESSORIES W/STUDS	SCOPE BASE	L/SIGHTS	

TO:	SHIP TO:
AHLMANS ROUTE 1 BOX 20 MORRISTOWN USA	AHLMANS ROUTE 1 BOX 20 MORRISTOWN USA
MN 55052	MN 55052

INVT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 9-16-91	VIA UPS
-------------	--------------------	--------------------------------	------------	------------	----------------------	------------

UR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-----------	-----	-----------	-----	-------------	-------

IN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

TOWERS REQUEST

Discharges when bolt is closed.

FAULT: Could not duplicate complaint. However, disassembly of rifle revealed upper assembly has been improperly adjusted out of factory - 1) trigger will blow open at 2 pounds, 2) insufficient over travel. Since rifle is loaded with dirt and dust also. Improper maintenance.

Send repair quotation for cleaning and new trigger assembly (at normal cost, as good-will gesture)

REPAIRMAN JE	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6923 REV. 7/90

PPS 00089