

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN: JACK KAST

ORDER

94-14821

CUSTOMER ORDER NO.

L/FRONT SIGHT

RECOIL PAD NOT OF OUR MFG.

RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/02/94

05/03/94

BW 1-72

6516093

700

30-06

ADL

ESSORIES

L/STUDS

F. Supply

M:

SHIP TO:

LEE AIKINS SPORT SHOP
245 N MAIN
POCATELLO

ID 83204

LEE AIKINS SPORT SHOP
245 N MAIN
POCATELLO

ID 83204

CUST NO: 001144 B.O.D

QUANTITY

ACCOUNT NUMBER N/C

WRITE

☐

PROM. DATE

ESTIMATED

VIA

UPS

CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

STOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

BLE

A1

B1

3GER GROUP

T ASSY.

IREL ASSY.

X ASSY.

OD

TAL

IF FAULT

Gun goes off when disengaging the safety

Mfg. 1-72 Unable to duplicate customer concern as received. Trigger has been adjusted outside of the factory and inside of Housing is loaded with excessive amber colored grease. Trigger should not be altered outside of the factory and only light film of light oil. 'Like Rem oil' is required for maintenance and storage. Exchange Trigger Assy. at a special price as a gesture of good will and to restore customer confidence.

IS

COMMENTS

Trigger pull measured 4 to 4 1/2 lbs as received and now lift measured .009

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 1/94

PPS 00091