

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER R92-26614	
INITIAL	CUSTOMER ORDER NO.						
FPS		DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/02/92		12/08/92	DU 9-71	6482497		700	7MM MAG ADL
ACCESSORIES		W/STUDS		SCOPE BASE			

FROM:	SHIP TO:
AKERS/LARRY 242 ROLLING ACRES PEARCY AR 71964	AKERS/LARRY 242 ROLLING ACRES PEARCY AR 71964

CUST NO: 071376 C.O.D	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C
WRITE ☐	CLEAN/TEST
PROM. DATE	ESTIMATED
	12/31/92
VIA	UPS
GUN CONDITION	REPAIR CHARGE
☐ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
☐ MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1		
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Trigger pull was inoperative. Trigger assembly has been adjusted outside the factory, trigger pull about factory specification, and the movement sluggish (gummy, resistance in trigger action). Gun engagement is insufficient at times if the bolt was closed that the firing pin does not lock, simply follow down on the cocking cam.

REPAIRMAN: JJB
PROOF: [check]
CLEAN: [check]
TEST: [check]
TARGET: [check]
PATTERN: [check]
GALLERY TESTER: [check]
DATE: [check]
DATE: [check]
DATE: [check]
DATE: [check]
DATE: [check]
DATE: [check]

OFFICE COPY

RD6925 REV