

~~CONFIDENTIAL~~

R-86-07765

serious

Allison Carey PT

alleged follow down - Doe

+ rig + rear worked on  
+ rig - light + lots of overtravel  
↳ 2 1/4 lb pull - way below  
Rem spec.

.065" rear lift - good + w/in spec.

Overtravel + pendage adjustment  
screws backed out of + rig arm

All + rig components are correct w/  
no defects. However, the

base + + rig overtravel  
screws have been adj. on back  
of Rem.

Overtravel adjustment is spec.  
correctly adjusted.

Not fault

W. etc. ready to go to Rem spec.  
w/ all + rig arm w/ your purchase  
(over)