

RECEIVING AND ESTIMATING REPORT

CUST NO: 005292 ILION		COMMENTS: W/1 SWIVEL		STEYK	
INITIAL JJM	CUSTOMER ORDER NO.				
DATE RECEIVED 10/18/91	DATE OPENED 10/22/91	DATE CODE DY 7-74	SERIAL NUMBER 6765646	MODEL AND GRADE 700 7MM MAG ADL	ORDER R 91-212
ACCESSORIES			L/SIGHTS		

FROM:

ALLISON & CAREY GUN WORKS
10218 S. E. POWELL BLVD.
PORTLAND OR 97266

SHIP TO:

ALLISON & CAREY GUN WORKS
10218 S. E. POWELL BLVD.
PORTLAND OR 97266

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE 10/28/91	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST "Customer says rifle fired twice when taken off safety"

MAIN FAULT: Cannot duplicate above complaint. However, it was noted that the trigger assembly has been adjusted outside of factory and is outside our specifications. 1) trigger pull measured at 2 1/2 pounds (trigger does not have positive indication) 2) over-travel is excessive. Also, it was noted that trigger assembly is extremely dirty and dirty. Ser-lyft "007"

REPAIRS: Clean trigger assembly (if possible) and re-adjust to factory specs. Or, offer new trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN AAR	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD4925 REV