

7-23-81 Rev. 2-19-81

MODEL: 600

GENERAL CONDITION: PAID

DATE: 7-23-81

WORK: SAFETY APPEARS TO HAVE BEEN REMOVED + REASSEMBLED WRONG

TIME AND TYPE: NOT KNOWN

QTY: 1

PROCP: V IMP: 62 TEST: 70

REMARKS: OK

WORKER OFFICE: OK

REMARKS: OK

CHARGE: OK

TEST:

COMPONENT CONDITION: (Damaged, Broken, Old Style)

BRIGHT METAL ON DBL. 3 LIGHT MARKS ON STOCK

SAFETY ARM BROKEN AT THUMB PIECE

SAFETY PIVOT PIN AND SAFETY PIVOT PIN

RETAINER WASHER REVERSED

COMPLAINT: FIRES ON CLOSING OF BOLT

INCIDENT:

COMMENTS: Unable to duplicate customer complaint.

5/8" Trigger Pull, 2095" seen left. Gun passed back test.

Replace fire control.