

R. 16125
w/788
GMM

COMPLAINT: FSR

7/15/82
R. J. J.

CUSTOMER'S F.C. w/ NEW SEAR & SPRING & PIN

SEAR LIFT: .0095
DBG D-42d55

OK WHEN ASSEMBLED TO CUSTOMER'S
ACTION
T.P. 3#

CUSTOMER'S F.C. w/ ORIGINAL PARTS

SEAR LIFT: .0055

F.S.R. → TRIGGER DOESN'T RETRACT

T.P. 1.6 #

- TRIGGER POLISHED
- SEAR SPRING ~~IS~~ SHORTENED
- SEAR BROKEN & REPAIRED AT PIVOT
HOLE & PIVOT HOLE REAMED OVERSINE.