

Remington.



# REMINGTON ARMS COMPANY, INC.

PETERS



SPORTING FIREARMS  
TRAPS  
POWDER METAL PARTS  
ILION, NEW YORK  
AMMUNITION, BRIDGEPORT, CONNECTICUT  
LONOKE, ARKANSAS

MANUFACTURERS OF  
SPORTING FIREARMS, AMMUNITION  
TRAPS TARGETS  
ILION, NEW YORK 13357  
TELEPHONE (315) 894-9961

PETERS CARTRIDGE DIVISION  
BRIDGEPORT, CONNECTICUT  
TARGETS, ADA, OKLAHOMA  
ATHENS, GEORGIA  
RINDLAY, OHIO  
CABLE—HARTLEY, BRIDGEPORT

December 23, 1985

Mr. Glen E. Anson  
Route 3, Box 173  
Perry, Oklahoma 73077

Dear Mr. Anson:

Reference is made to your letter of December 11, 1985, regarding the accidental firings you have experienced with your Model 700 270 Win. caliber rifle, serial number A6360662, when the safety was moved from the "safe" to the "fire" position.

We were indeed sorry to learn of your having a problem of the nature you described, as it is not representative of Remington quality, nor characteristic of the Model 700 rifle.

Generally, the type of malfunction you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or, from pressure being inadvertently applied to the trigger as the safety is being moved.

Please, at your convenience, return the rifle via U.P.S., Transportation C.O.D., to:

Remington Arms Co., Inc.  
Attn: J.A. Stekl, Supervisor  
Product Service Division  
Ilion, NY 13357

Be sure to boldly mark the two (2) butt ends of the outside of the package "STEKL", to expedite handling.

Upon receipt, the rifle will be thoroughly examined and, if it is found to be factory faulty, any necessary repairs will be made on a no-charge basis.

Thank you for bringing this matter to our attention and for affording us this opportunity to be of service to you.

Sincerely,

J.A. Stekl, Supervisor  
Product Service

JAS:tnn