

ORDER
R 91-26294

ACCESSORIES	W/STUDS	SCOPE BASE	L/SIGHTS
-------------	---------	------------	----------

FROM:	SHIP TO:
ARMBRUSTER, DUANE RR 1 BOX 96A FALLS CITY NC 68355 USA	ARMBRUSTER, DUANE RR 1 BOX 96A FALLS CITY NC USA 68355

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	---------

GUN CONDITION		REPAIR CHARGE
☐ NEW		EXCISE
☒ LIGHTLY WORN		TAX
☐ WORN		INSURANCE
☐ VERY WORN		UPS
☐ UNREPAIRABLE		PARCEL POST
		TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT			
CYCLE	A1	B1							
TRIGGER GROUP	Rifle has fired when safety was moved to the fire position and also when bolt was being lifted.					F1			
BOLT ASSY.						B3		E2	F2
BARREL ASSY.						B4			F3
REC. ASSY.						B5	D2	E4	F4
WOOD			C1	D3	E5	F5			
METAL			C2						

MAIN FAULT Unable to duplicate above complaints. Many attempts were made to make the rph malfunction, in these ways, without success. It was noted however, that the trigger assembly is oily and dirty, and that the trigger pull has been adjusted out of factory to 2 1/2 pounds. This is below our min. spec. spec - 3.0 to 3.5 lbs.

[illegible]