

**the Crosby group inc.**  
A DIVISION OF CROSBY

**BILL ASHBECK**  
DISTRICT REPRESENTATIVE

818-484-5853  
10080 100th PLACE  
MAPLE GROVE, MN 55369

BLVD  
850  
E W  
LDA  
81-5770

326 GENEVA AVENUE  
OAKDALE, MN 55063  
331 UNIVERSITY AVE  
ST. PAUL, MN 55101

E 1265

2001 WOODBURY  
ROSEVILLE, MN 55127  
1751 SO. ROBERTS ST.  
ST. PAUL, MN 55105

Dear Mr. Potter 7-1-85  
Per our conversation, Week of 7-1-85  
about my Remington Model #600 Serial  
#84057 308 cal.  
Rasa Jikkila of Rigging and Wear  
telling, Mr. witness the accident.  
Enclosed is an estimate for the window  
I had done in 1983. The bullet ripped a little  
cloth and lodged into the right window frame.  
I did repair the cloth and just put padding  
in the door frame.  
I purchased the gun in 1968, new  
from the Kaiser Blauherz, ~~the Kaiser Blauherz~~  
club in Germany.  
I would just please repair the gun  
and reimburse me for the new window  
the gun shot out.  
Please put a new pad on the butt  
I will pay for it.  
P.S. I would like to hunt ~~the~~ ~~deer~~ ~~again~~ ~~the~~ ~~fall~~.  
Bill Ashbeck

DATE 7-1-85	
RESIDENCE PHONE	
BUSINESS PHONE	
UNIT PRICE	AMOUNT
288.05	232.14
bro	37.90
Ket	375
W	19.06
	276.35

near safety cam from firing pin from moving "on", there is no way the primer and fire the is a mechanical impossibility engaged.

the rifle upon safety the trigger, and no mal- After numerous attempts to fire the rifle upon safety engagement and upon safety release, the only manner in which your rifle was made to fire was to release the safety and to pull the trigger.

Even though your Model 600 is involved in a trigger modification program, the trigger mechanism in your particular firearm is in safe, proper working condition. Only a small percentage of the