

# RECEIVING AND ESTIMATING REPORT ✓

|                           |                         |                            |                         |                                  |  |                    |  |
|---------------------------|-------------------------|----------------------------|-------------------------|----------------------------------|--|--------------------|--|
| INITIAL<br>JJM            |                         | CUSTOMER ORDER NO.<br>1487 |                         | COMMENTS                         |  |                    |  |
| DATE RECEIVED<br>10/23/90 | DATE OPENED<br>10/25/90 | DATE CODE<br>XL 12-64      | SERIAL NUMBER<br>132398 | MODEL AND GRADE<br>700 30-06 ADL |  | ORDER<br>R 90-2812 |  |
| ACCESSORIES               |                         |                            |                         |                                  |  |                    |  |

FROM:

B & R GUNS  
11 W. SAINT JOSEPH ST  
PERRYVILLE MO 63775

SHIP TO:

B & R GUNS  
11 W. SAINT JOSEPH ST  
PERRYVILLE MO 63775

|                |                    |                                |            |            |           |            |
|----------------|--------------------|--------------------------------|------------|------------|-----------|------------|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | CLEAN/TEST | PROM. DATE | ESTIMATED | VIA<br>UPS |
|----------------|--------------------|--------------------------------|------------|------------|-----------|------------|

|               |     |           |     |             |       |
|---------------|-----|-----------|-----|-------------|-------|
| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---------------|-----|-----------|-----|-------------|-------|

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *The customer said he has a problem that the rifle won't shoot holding it in the horizontal position and when he pointed it up to remove the ammo the shell went off.*

MAIN FAULT: *Could not duplicate above complaint. However, it was noted that firing pin fell is somewhat slow. Removal of stock disclosed that trigger assembly is contaminated with solidified oil(?) and dirt. Cold temperature could possibly aggravate this condition.*

PARTS: *Send repair quotation to replace trigger assembly at 1/2 normal price, as gesture of good-will.  
Rifle is 26 years old*

|                 |       |       |      |        |         |
|-----------------|-------|-------|------|--------|---------|
| REPAIRMAN<br>BW | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER  | DATE  | DATE  | DATE | DATE   | DATE    |

OFFICE COPY

RD6925 REV. 7/90