

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 92-24410

ATTN FRED EMHOF

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/12/92

11/12/92

DX 9-73

6673330

700 6MM

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

BAKER, STAN
314 POWELL AVE
P O BOX 338
DUNN

NC 28334

BAKER, STAN
314 POWELL AVE
P O BOX 338
DUNN

NC

28334

CUST NO: 070023 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☒ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Could not duplicate complaint. However, it was noted that the trigger assembly had been adjusted out of factory (excessive trigger pull and sear engagement was insufficient). When the bolt was cycled fast, the firing pin would not strike properly, falling down on the cocking spring. Also, there is excessive oil and contamination on the trigger assembly. Trigger pull 24 pounds; sear lift .008".

COMMENTS

Based on condition of trigger assembly and the fact that the sear engagement has been improved with, after new trigger assembly at normal cost, was given a good will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE