

3-3/528-333

P.I. 155 GUN EXAMINATION REPORT NUMBER: 5 - MODEL: 660

GENERAL CONDITION: USED R #: 16659

OUTSIDE WORK: SCREW DRILL - 1/8" DATE: 1-1-71

FIRED AMMO TYPE: 7.62x39mm FROM: BOB BAKER

& CONDITION: GOOD GUN #: 12532

PROCP: 950 INSP.: 74 TEST: 36 CODE: PL-2-64

HEADING: 04 GA./CAL.: 222

BREECH OPENING: 04 CHECKED BY: 11-1-000

RECOIL SHOULDERS: 04 APPROVED: 5/1/71

CHAMBER: 04 APPROVED: 5/1/71

TEST: 04 APPROVED: 5/1/71

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 5/1/71

SLIGHT BENT - 1/8" - 1/4" - 1/2" - 3/4" - 1"

1/2" - 3/4" - 1" - 1 1/4" - 1 1/2" - 1 3/4" - 2"

COMPLAINT: FIRE WHEN BOLT IS LOCKED

FORWARD

INCIDENT:

COMMENTS: Serial 007. Gun & Safety cam has

sluggish action due to gummy substance on these
parts. This condition could have contributed to incident

Replace trigger assembly. W/180