

May 24, 1980

Dear Sir,

Enclosed you will find two 600 Mohawk rifles which have gone off as the bolt is locked forward.

We understand you have had problems with this model and that you put on a different trigger assembly.

The one went off in my house, ruined the barrel of another gun in the wall, which caused metal pieces to fly around the room. One person was injured. It could have been a very fatal case.

Thank you,

Bob Benge  
Campe, Colorado  
81029

17469  
COMPLAINT:

FORWARD

INCIDENT:

COMMENTS:

Serial 007. Bear & Safety cam has  
sluggish action due to greasy substance on these  
parts. This condition could have contributed to incident.

Replace trigger assembly.