

FEB. 7, 1990
2641 MENDOCINO
CORPUS CHRISTI, TX.
78418

REMINGTON ARMS CO. INC.
ARMS SERVICE DIV.
ILLION, NEW YORK
13557

DEAR SIR,

MY REMINGTON MODEL 700 .270 CAL RIFLE,
SERIAL # A6898471, HAS MISFIRED FROM THE SAFETY
POSITION TO THE FIRE POSITION.

THREE TIMES IT INADVERTANTLY FIRED AS I UNLOADED.
ONE TIME IT FIRED AFTER I HAD LOADED FOUR CARTRIDGES
IN THE CLIP, ONE IN THE CHAMBER. I PLACED IT ON SAFE
THEN AS I MOVED IT FROM SAFE TO FIRE POSITION, THE
RIFLE FIRED.

I ENCLOSE THE RESULTS OF AN INSPECTION FROM
CHARLEY'S GUN SHOP. I HAVEN'T FIRED IT SINCE.

I UNDERSTAND THERE WAS A RECALL OF THIS MODEL
ABOUT 34 YEARS AGO. THIS GUN IS IN THAT RANGE.

PLEASE DO WHAT YOU CAN TO SQUARE THIS PROBLEM
AWAY. I'LL FEEL A LOT SAFER.

SINCERELY,
Quincy J. Bonfield

512 937 5862