

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
LCS		2715					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	BDL	ORDER	
11/08/90	11/08/90	DE 7-84	B6603814	700 7HMMAG		R	90-294
ACCESSORIES		W/STUDS					

L/ REAR SIGHT

FROM:

BARTS SPORTS WORLD
6814 RITCHIE HWY.
GLEN BURNIE MD 21061

SHIP TO:

BARTS SPORTS WORLD
6814 RITCHIE HWY.
GLEN BURNIE MD 21061

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					12-3	UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *discharged twice while taking the safety off, cost #2 will not retain in the mag. when cost #1 is being ejected*

MAIN FAULT *cannot duplicate complaint, however the safety "off" force is higher than normal.*

PARTS	1) Because of higher than normal safety "off" force, replace trigger assembly at no charge					
	2) Check rifle for proper feeding - make any necessary corrections					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	BWT					
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7