

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R # : 002023
OUTSIDE WORK: No DATE: 1-27-72
FROM: BAY CITY HDW. CO.
FIRED AMMO TYPE: — BAY CITY, MICH.
& CONDITION: _____ GUN # : 6500965
PROOF: R.E.P.-M ASSEMBLER 79 INSP.: — TEST: 13 CODE: NONE
HEADING: O.K. GA./CAL.: 243 WIN.
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

MINUS STOCK. TRIGGER PULL 4½ LBS. - O.K. ENGAGEMENT
.008 (.020 MIN.) NEW RIVETED HOUSING. CONNECTOR
1.093 M/D = 1.080 TRIGGER 1.076 M/D = 1.076
1.083 BURRS ON
CONNECTOR SIDES.

COMPLAINT: "FIRES ON SAFE"

INCIDENT: MAY HAVE FOLLOWED DOWN WHEN SAFE WAS
RELEASED.

COMMENTS: ENGAGEMENT IS SET TOO CLOSE. WITH THE
BURRS ON THE CONNECTOR AND CLOSE ENGAGEMENT,
IT IS POSSIBLE THAT THE CONNECTOR FAILED TO
RETRACT WHILE THE SAFETY WAS ON THEN FOLLOW
DOWN OCCURRED WHEN THE SAFETY WAS RELEASED.