

## CEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

CUSTOMER ORDER NO.

Product Service ✓ R 2-93 25851

|          |             |           |               |                   |                 |
|----------|-------------|-----------|---------------|-------------------|-----------------|
| RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE |
| 12/22/93 | 12/02/93    | SV 3-79   | A6786035      |                   | 700 30-06       |
| SERIES   | W-8700      |           |               |                   |                 |

SDL

Fred Suppy

BAYVILLE SPTG GOODS INC  
259 BAYVILLE AVE  
BAYVILLE

NY 11709

SHIP TO:

BAYVILLE SPTG GOODS INC  
259 BAYVILLE AVE  
BAYVILLE

NY 11709

CUST NO: 011859 C.O.D.

|               |                    |                                |            |           |               |
|---------------|--------------------|--------------------------------|------------|-----------|---------------|
| INT NUMBER    | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | PROM. DATE | ESTIMATED | VIA           |
|               |                    |                                |            | 12/16/93  | 5640479750    |
| CONDITION     |                    |                                |            |           | REPAIR CHARGE |
| NEW           |                    |                                |            |           | 25.00         |
| SLIGHTLY WORN |                    |                                |            |           | EXCISE        |
| ORN           |                    |                                |            |           | TAX           |
| VERY WORN     |                    |                                |            |           | INSURANCE     |
| UNREPAIRABLE  |                    |                                |            |           | UPS           |
| VARIED        |                    |                                |            |           | PARCEL POST   |
|               |                    |                                |            |           | TOTAL         |

| COMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|---------------|------|----------|--------|----------|-----|---------|
| E             |      |          |        |          |     |         |
| BER GROUP     |      |          |        |          |     |         |
| ASSY.         |      |          |        |          |     |         |
| REL ASSY.     |      |          |        |          |     |         |
| ASSY.         |      |          |        |          |     |         |
| D             |      |          |        |          |     |         |
| L             |      |          |        |          |     |         |
| FAULT         |      |          |        |          |     |         |

"When rifle is moved to the firing position, the firing pin repeatedly misses primers"

Upon receipt, unable to duplicate customer concern. However examination reveals that the bolt stop release and rear safety can only be shipped from the factory and trigger assembly being covered with sticky waxy substance. Rifle mfg 1979

COMMENTS

Replace complete trigger assembly & clean action at 1/2 normal cost, as gesture of good will

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN      | PROOF | CLEAN | TEST | TARGET | PATTERN |
| JTB            |       | ✓     | ✓    |        |         |
| GALLERY TESTER | DATE  | DATE  | DATE | DATE   | DATE    |

OFFICE COPY

RD6925 REV. 1-82

PPS 00386