

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-20041

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED
09/23/92DATE OPENED
10/02/92DATE CODE
CL 4-91SERIAL NUMBER
7675320

NEW SERIAL NUMBER

MODEL AND GRADE
7 308 WINACCESSORIES
W/STUDS

FROM:

BBJ'S
448 HWY 46
DICKSON

TN 37055

SHIP TO:

BBJ'S
448 HWY 46
DICKSONTN
37055

CUST NO: 058517 C.O.D L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE IN ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Disassembly of rifle revealed dirt and rust on bottom of barrel, receiver and on and off trigger assembly. Rust inside of trigger assembly is causing internal trigger parts to bind and not move freely. Consequently, bolt would not cock - rifle was inoperable.

Trigger assembly became wet and dirty during use and was not cleaned after. Inadequate maintenance.

ARTS

COMMENTS

Change to clean rifle and replace trigger assembly.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE