

RECEIVED

FEB 27 1987

E.F. C. 111-102

HERBERT J. BEIL, M.D.  
658 WEST MARKET STREET  
LIMA, OHIO 45801  
PHONE 229-0816

February 24, 1987

Mr. Edward Sienkewicz  
Remington Arms Company, Inc.  
Product Service  
Ilion, New York 13357

Dear Mr. Sienkewicz,


As we discussed the other day on the telephone, I own a Remington Model 700  
LM 7 mm Magnum (No. 36532467). This was purchased 9/27/84. The initial  
problem with the weapon was an unreliable extractor. The weapon was sent in  
and this taken care of adequately.

However, I have remained unhappy with the weapon, in that the bolt will not  
remain in the down and locked position when the safety is on. I used the  
gun to hunt in rugged country and carried the gun with a sling on my back.  
On several occasions, the bolt handle would open up and the round would fall  
out of the chamber and be lost. I had to improvise to avoid this by putting a  
rubberband around the trigger guard onto the bolt handle. This works well in  
warmer weather, but in sub-freezing is quite inadequate.

As we discussed, a modification is now possible to remedy this and restore  
the action to a bolt lockdown and secure position when the safety is on. I  
would kindly request that this bolt be modified accordingly and will be send-  
ing the rifle back shortly by UPS.

Thank you for your kind attention.

Sincerely,



Herbert J. Beil, M.D.

SHIP GUN AFTER APRIL 155

rk