

MARCH 23, 94.

TO REMINGTON ARMS,

I AM WRITING THIS LETTER
BECAUSE OF THE FOLLOWING
PROBLEMS WITH MY 270 RIFLE
MODEL 700 WITH SCOPE.

MY 270 RIFLE DELAYS FIRING
WHEN YOU PULL THE TRIGGER FOR
ABOUT FIVE TO TEN SECONDS
BEFORE IT FIRE'S ON THE FIRST
SHOT MOST OF THE TIME. ON A
FEW OCCASSIONS IT HAS FIRED
WHEN YOU TAKE OFF THE SAFETY.
ON ANOTHER OCCASSION MY
HUNTING BUDDY WAS LOOKING AT
THE RIFLE AFTER THE RIFLE
DELAYED, IT FIRED IN TO THE
WOODS. WHEN HE PUSHED THE
SAFETY OFF THE RIFLE FIRED.

PLEASE FIX THIS PROBLEM.
IF YOU HAVE ANY QUESTION
PLEASE FEEL FREE TO GIVE
ME A CALL (813) 535-0904
AFTER 5:00 OR LEAVE A → ~~CALL~~ ^{MESSAGE}