

RECEIVING AND ESTIMATING REPORT

INITIAL

CUSTOMER ORDER NO.

COMMENTS

Product Service

ORDER

R93-24101

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/04/93

11/09/93

CK 4-90

C6527598

700 243 WIN BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM

SHIP TO

BERNS, KENT

WINKY GUNSHOP

RR 1 BOX 175

CHURDAN

IA 50050

CUST NO: 086931 C.B.D

IA 50050

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

PROM. DATE

ESTIMATED

VIA

WRITE

11-19-93

UPS

GUN CONDITION

REPAIR CHARGE

☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

25.6

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5			E4	F4
WOOD		G1			E5	F5
METAL		C2				
MAIN FAULT						

Upon receipt, unable to duplicate problem with concern.

Inspected barrel that the trigger adjustment & stop screw had been tampered with on both parties.

Replaced complete trigger assembly and then action set to 1/2 normal adjustment. Cost, as stated, is good will.

Go ahead

Victor Paul m/c

5437-0002-1031-7113

Up Jan 96

Phone 515-296-0388

REPAIRMAN

PROOF

CLEAR

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

25 REV. 1/9