

Return  
to →

Kent Berns  
Winky Gunshop  
RRI Box 175  
Churdon IA 50051

(515) 389-3794  
Weekends  
(515) 296-0388 Work  
(515) 232-7170 Work

Dear Sir:

I enclosed my Remington Model 700 BDL  
243 serial # C6527598.

The problem is the trigger. When I  
got the gun out this fall, it would fire the  
~~ten~~ minute the safety was put on Fire.  
If I ~~worked~~ worked the bolt with the  
safety off, it would fire when the bolt  
was closed. I also noticed that the trigger had a lot of travel.

I then took the gun apart and adjusted  
the trigger ~~stop~~ stop screw. It was adjusted  
according to your instruction manual for the  
least amount of trigger overtravel. It took considerable  
adjustment.

When I put it back together, the gun would not  
fire until the trigger was pulled. But the trigger  
~~the~~ tension was only two pounds. I didn't try adjusting  
the pull of trigger screw.

Please do whatever it takes to fix the problem.  
Luckily nobody got hurt. It is possible that some  
rem oil seeped down into the trigger assembly.

My GM Mastercard # 5437 0002 1031 7113  
expires 01/96

The Gun was bought new from Bill Hicks  
Company (a wholesaler) in January 1991