

700 Prod. Corp

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 025940
OUTSIDE WORK: BUTT PAD ADDED, TRIGGER DATE: 12-15-72
PULL RE-ADJUSTED. FROM: BEST PRODUCTS
FIRED AMMO TYPE: _____ HAMPTON, VA.
& CONDITION: _____ GUN #: 6517902
PROOF: R.E.P.-B ^{ASSEMBLER 79} INSP.: 58 TEST: 97 CODE: BW = 1/72
HEADING: O.K. ON INSPECTION MAX. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER BINDING ON GUARD, TRIGGER PULL ADJUSTED
DOWN TO 2-2½ LBS. BY CUSTOMER. EXCESSIVE LUBRICANT.

COMPLAINT: GUN FIRES WHEN SAFETY IS RELEASED.

INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED,
HOWEVER WITH TRIGGER PULL REDUCED BELOW
SPECIFICATIONS (3 TO 5 LBS.) THE BINDING TRIGGER
PROBABLY DID NOT RETRACT SUFFICIENTLY TO COCK THE
FIRING PIN.