

Caral Campbell

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: GOOD R #: 23155
OUTSIDE WORK: NO DATE: 11-18-71
FROM: BIGGS SPT. GDS.
FIRED AMMO TYPE: - PENSACOLA, FLA.
& CONDITION: _____ GUN #: 6344022
PROOF: R.E.P.-A INSP.: J TEST: 87 CODE: KT-5/70
HEADING: O.K. GA./CAL.: 22-250
BREECH OPENING: - CHECKED BY: C. PROVER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTS.

TRIGGER CONNECTOR 1.091 (MID-1.098) TRIGGER 1.068 (MID-1.078)
CONNECTOR - SEAR ENGAGEMENT 0.030 MIN. .015, TRIGGER
PULL: 4 TO 4 1/2 LBS. LUBRICANT USED APPEARS TO BE TOO
HEAVY.

COMPLAINT: WHEN PUSHING SAFETY OFF THE GUN GOES OFF.

INCIDENT: FOLLOWED DOWN.

COMMENTS: WITH THE EXCESSIVE CLEARANCE BETWEEN THE
TRIGGER CONNECTOR AND TRIGGER AND HEAVY LUBRICANT,
THE TRIGGER CONNECTOR PROBABLY WORKED UP UNTIL
IT CAUGHT ON THE SEAR, FAILING TO RETRACT INTO
COCKED POSITION, PUSHING THE SAFETY OFF, THEN HAVING
RELEASED THE FIRING PIN FORWARD TO STRIKE THE PRIMER.