

P.I. 50 GUN EXAMINATION REPORT NUMBER: 219 MODEL: 700-002
GENERAL CONDITION: FAIR R #: 10000
OUTSIDE WORK: REAR SIGHT REMOVED DATE: 3-25-80
SCOPE BASE ADDED FROM: 26542 BILLYS
FIRED AMMO TYPE: NOT KNOWN MESA 1012
& CONDITION: _____ GUN #: 6524577
PROOF: (REM) M INSP.: 9 TEST: 97 CODE: 11-2-72
HEADING: OK GA./CAL.: 2506
BREECH OPENING: OK CHECKED BY: JA-4-80
RECOIL SHOULDERS: OK APPROVED: JAH 4/23/80
CHAMBER: OK APPROVED: RE 4/23/80
TEST: _____ APPROVED: W.B. 4/23/80
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: Q.B. 4-23-8

SLIGHT MARKS ON BRASS

BRIGHT METAL MARKS ON BRASS

COMPLAINT: FIRED WHEN SAFETY WAS MOVED TO OFF

INCIDENT: _____

COMMENTS: Sear lift .0095", Trigger Pull 4", Passed
Trick Test.

Fire control adjusting screws possibly adjusted
outside of Remington and resealed with red sealant.

Unable to duplicate customer complaint.