

*Lucas
Jim STEKL*

T.H. Blakeney
Box 337
Clinton, Arkansas
8 October 1985

Firearms Product Manager
Remington Arms Company, Inc
939 Barnum Ave
P.O. Box 1939
Bridgeport, Connecticut 06601

Dear Sir:

On 7 June 1985 I purchased a .38mmBR Pistol Serial #B7518994. It took me a couple of months to get it scoped and bullet moulds ordered etc. For the first few rounds fired it done OK, however with continued firing the forearm pulls away from the BARREL Approximately $\frac{1}{4}$ " and the groups fired are about twice as high as they are wide. Having never owner a nylon stock before is this pulling away from the barrel normal? Don't look too good but ~~XX~~ I taped the stock and barrel together with nylon tape and that seems to help a bit. Please advise if this is normal??

Thanks:

T.H. Blakeney
T.H. Blakeney

RECEIVED
OCT 22 1985
CONSUMER SERVICE

RECEIVED

OCT 28 1985

J. A. STEKL