

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: GOOD R # : 002116

OUTSIDE WORK: SCOPE MOUNTED - REAR SIGHT DATE: 2-1-72

REMOVED

FROM: BLISH, MIZE & SILLMAN INC.

FIRE AMMO TYPE: -

ATCHISON, KANSAS

& CONDITION: _____

GUN # : 6362366

PROOF: R.F.R.-E INSP.: 73 TEST: 13

CODE: WT = 8/10

HEADING: _____

GR./CAL.: 270 WIN.

BREECH OPENING: O.K.

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO BROKEN, ETC. COMPONENTS. SIDE BURR ON TRIGGER
& CONNECTOR. TRIGGER FULL STROK. ENGAGEMENT .007 (MIN.
IS .020) NONE OF SCREWS SEALED. ENGAGEMENT
SCREW STAKED BUT NOT HOLDING. LOADED CARTRIDGE
ON CONNECTOR NOT HORIZONTAL.

COMPLAINT: RIFLE FIRED PREMATURELY,

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF INSUFFICIENT ENGAGEMENT &
BURRS PROBABLY PREVENTED THE CONNECTOR-TRIGGER
FROM RETRACTING INTO FIRING POSITION CAUSING THE
FIRING PIN TO FOLLOW DOWN.