

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 04/05/93
ENTER REPAIR NUMBER -----> 9223376 09 17 32
SERIAL NO: B6277549 NEW SERIAL NO:
FROM: (CUST NUM: 008349) BOBSARMYNA MODEL: 700
BOBS ARMY & NAVY GA/CAL: 7MM MAG
C/O NBS TYPE: ADL
229 E MARKET ST ACCESSORIES: W/STUDS
CLEARFIELD PA 16830
SHIPPED TO:

DATE CODES: BB 1-81
OTHER ACCESSORIES:
L/REAR SIGHT

COMMENTS:

DATES:		TO	FROM	
RECEIVED	10 29 92	GALLERY	00 00 00	00 00 00
OPENED	11 04 92	PROD SERV	11 17 92	11 18 92
ESTIMATED	11 19 92	TAG GUNS	00 00	
PROMISED	00 00 00	REJECTED	00 00	
REPAIRED	00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE: W
SHIPPED	01 29 93			

BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9223376 REPR NOT AUTHORIZED WILM INVOICE PR 04/05/93
CUSTOMER NAME: BOBS ARMY & NAVY 09 17 45

REQUEST: "GUN DISCHARGES ON OCCASION WHEN COCKING WEAPON"
MAIN FAULT: NO FAULT FOUND - CANNOT DUPLICATE ABOVE COMPLAINT & CANNOT
MAKE RIFLE MALFUNCTION IN ANY WAY. RIFLE OPERATES PROPERLY
IN ALL RESPECTS.
TRIGGER PUL 5 POUNDS; SEAR-LIFT .007"
DATE OF MFG: 01-81

PARTS: \$ 0.00 1 26345 TRIGGER ASSEM RH
\$ 0.00 19900005 TEST
LABOR: \$ 0.00 1. RETURN RIFLE AS-IS
\$ 0.00 2. INSTALL NEW TRIG ASSEMBLY AT 1/2 NORMAL COST, AS A
\$ 0.00 GESTURE OF GOOD-WILL, IF THAT WILL BETTER RESTORE
\$ 0.00 CONFIDENCE IN THE RIFLE.
\$ 25.00 TRIGGER ASSEM - 1/2 PRICE
\$ 0.00 39-D/A 111-9450
\$ 0.00 HB/HAR
\$ 0.00 ** RETURNED AS RECEIVED - CUSTOMER'S PROPERTY

REPAIRMAN'S INITS: HB NUM OF WKS: 00 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 0.00 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR

*Customer gave us go ahead early Jan 93 - per Jim
at Bob's - We set as rec'd?
a note ... it all ... neither of them will*