

**Remington.**



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

May 05, 1986

Mr. Enrique Borgheresi  
P.O. Box 8063  
Greenville, SC 29604

Dear Mr. Borgheresi:

This is in reply to your thoughtful letter of 03/18/86 regarding your godson's son and the returned Mohawk 600 rifle, serial #A6612793. Of course, we are pleased that the boy has recovered with no ill affects.

Our expert's examination showed that the sear lift at full safe is .006", and the trigger pull averaged out at 3-1/2 pounds. Sear engagement is .020-.025". In short, everything checked out fine.

Numerous attempts to prompt an accidental discharge failed as the rifle operates normally in every respect and is a safe firearm. Therefore, our experts concur with your professional opinion that the only way to discharge the firearm is to pull the trigger with the safe in the "fire" position.

We are returning the rifle, prepaid, to your attention in the condition as received.

Enclosed for the boy is a Remington "First In The Field" belt buckle. Please pass it on with our compliments.

Thanks for calling the matter to our attention, Mr. Borgheresi, and we wish you every business success. Also, many thanks for your past and present support of our products. We're glad we could be of service to you.

Sincerely,

  
R. H. Potter, Supervisor  
Product Service

RHP/cal  
Enc.