

*file* → *Fred Supry*

The following are the mailing control headers

To: GREENKD@SLINK:Kenneth D. Green

Copies-To: - @ X400GW{/c=US/a=MCI/p=DUPONT1/o=DUPONT/ou=-/ou=CDCV/

: M1/ou=(SANITADJ)/s=Sanita/g=Dennis-J}

: BUNTINJM@SLINK:Jay M. Bunting

From: WOHLWA@SLINK:William A. Wohl, Sr.

Subject: Please help...

Date: 24-Apr-1994 20:52:54

Date-delivered: 24-Apr-1994 22:53:08

Date-received: 25-Apr-1994 11:06:30

Subject: Please help...

Ken, I was in Missouri on a writer's turkey hunt and visited a good Remington dealer. While there, he showed me a Model 700 BDL SS that needs to be examined right away by you and Dennis. The store owner says he's had a fire-on-bolt-closing. Further, I examined the gun, and noted movement in the firing pin carrier upon movement of the safety -- which I understand is indicative of problem. I have told the guy that someone from your office will call and provide information on how to return the gun to Illinois.

*MR.* bosco roberts (owner), bosco's gun club, lancaster, MO 816-457-3919

thanks. Bill

*Hwy 63 S*

*63548*

*4/29/94 Called Mr. Roberts*

*Stated bolt doesn't seem to work properly?*

*Comments*

*Where is alleged*

*Call try to pick up*

*ef?*