

(E) XACT

10/02/71
09 59

9-30-91

MODEL: 700

GA/CAL: 30-06

TYPE: BDL

ACCESSORIES: W/STUDS

Phone:

(504) 882-7392

Remington Arms Co, Inc

Arms Service Div.

Iffron, New York, 13357

TS: WU 8-71

IER ACCESSORIES:

REAR SIGHT

Dear Sirs,

Sen. # 6471674

I purchased the accompanying
model 700 BDL 30-06 in approx. 1972.

0
0

ENTERED BY: LCS

REPAIRMAN:

TYPIST:

CORRESPONDENT:

PF3 = PRINT RME

At the time and to date, the
only way to clear a round from
the chamber is to put the safety
on fire and then work the bolt.

I have never felt comfortable
with this procedure. Is this
normal? Please reply.

CAROL M.

During our last hunting
season the weapon began
acting strangely and dangerously.
The problems are:

1. 12. 13

1. When attempting to move
the safety from safe to fire
and a round is in the chamber
the weapon automatically fires.

FROM

PACKAGE NO.

17024

