

RECEIVING AND ESTIMATING REPORT

COMMENTS

*To Product Service*ORDER
R 93-13398

INITIAL FPS	CUSTOMER ORDER NO.				
DATE RECEIVED 06/09/93	DATE OPENED 06/10/93	DATE CODE RR 11-68	SERIAL NUMBER 379389	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN BDL
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS	

FROM: *Setup full*
BRAUN, FRED
SPORTING GOODS
405 OVERLAND STREET
KENAI

AK 99611

SHIP TO:
BRAUN, FRED
SPORTING GOODS
405 OVERLAND STREET
KENAI

AK 99611

CUST NO: 079973 C.Q.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	FROM DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	-----------	-----------	------------

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE <i>2500</i>
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	N	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD				D3	E5	F5
METAL			C2			

MAIN FAULT

*Left mfg 1968 upon receipt rifle does not cycle, firing pin
follows down. Examination revealed that the trigger adjustment
and stop screw have been altered without policy, also found trigger
pin rusty.*

PARTS	COMMENTS
	<i>Replace trigger assembly completely and clean action at 1/2 normal replacement cost at option of your mfr. Go ahead</i>
REPAIRMAN <i>BFA</i>	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTER	DATE