

74N A6283152
BOLD 3152

Dear Sir

I Am RETURNING my 700 BDL
2506 RIFLE BECAUSE THE
TRIGGER IS NOT WORKING AS
IT SHOULD IT HAS FIRED
when you push the safety
OFF IT HAS done this
more than once. I had
A gunsmith check it and
talked to your service people
they said to RETURN IT.

Richard Brennehan
RD 3 Box 356V
Huntingdon, PA.

16652

Phone 814-643-5296

IG REPORT

5-06 BDL ORDER R 90-333

SHIP TO:

BRENNEMAN, RICHARD
RD 3
BOX 356V
HUNTINGDON

PA
16652

PROM. DATE ESTIMATED VIA
UPS

PARCEL POST TOTAL

WORN ☐ MISUSED ☐ MARRED

it should it has fired

trigger assembly has been
sent minus from all
me. at 24-2 1/2 pounds, 2)
at fully situation working

the trigger pull has been made off too far

Send again sent for new trigger assembly
at 2 normal cost, as gesture of good-
will.

Rifle is 15 years old

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY