

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 09/20/90	DATE OPENED 10/02/90	DATE CODE WQ 8-78	SERIAL NUMBER A6452288	MODEL AND GRADE 700 30-06 BDL/LH		ORDER R 90-25	
ACCESSORIES W/STUDS		L/SIGHTS					

FROM:

BRIDGES, DAVID C
121 BOBOLINK DR
GRIFFIN GA 30223

SHIP TO:

BRIDGES, DAVID C
121 BOBOLINK DR
GRIFFIN GA 30223

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	FROM DATE	ESTIMATED 10-8-90	VIA UPS
----------------	--------------------	--------------------------------	-----------	-----------------------------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST *Discharged 5 times unexpected*

MAIN FAULT: *Trigger Assembly contaminated with gummy, sticky substance. Firing pin fall slow because internal trigger parts are not moving freely - near safety catch sticking to side plate of assembly. Over travel adjusted improperly causing jamming. Although complaint cannot be duplicated let room temperature, colder temperatures could cause reported problem considering condition of trigger assembly.*

PARTS: *Trigger pull 4 1/2 #, rear lift .0105". Rifle improperly maintained*

Clean trigger assembly (if possible) and re-adjust over travel. If above not possible, offer replacement trigger assembly at full normal cost, as gesture of good-will

REPAIRMAN WBA	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY