

8-26-88

bcc R88-20530

P.S. Holding gun for rep.

Dear Mr. Brooks:

- ¶ Examination has been completed on your Model SEVEN rifle, serial# 7693688, which you returned for evaluation.
- ¶ *→
- ¶ Our examining expert gauged the trigger pull between $4\frac{3}{4}$ and 5 pounds. The rear left measured .012" and the sear-connector engagement is excellent. All these specifications are well within Remington ~~safety standards and prohibit the rifle from firing accidentally.~~ specifications
- ¶ Repeated attempts were made to make the rifle ~~follow down~~ ~~sear~~ follow down (fire upon bolt closing) with no malfunction. ^{Repeated} ~~Similar~~ attempts were made to make the rifle fire upon safety release, ~~with~~ again, with no malfunctions.
- ¶ In short, the trigger assembly ~~could not~~ was found to be safe in every respect and could not be made to malfunction. The only way the gun was made to fire was to ~~release~~ remove the ~~Based upon the~~ safety switch from the safe to the fire position and to pull the trigger.